SAFETY REPORTS

October 03, 2016

Steve Smith Safety Director Best Company 1234 Main Street Kansas City, MO 64555

Re: General Industry Safety Survey

Omaha, NE

Steve,

This report is in follow-up to the safety survey completed on October 02, 2016. The purpose of the survey was to identify potential safety hazards and/or OSHA violations. Tim Miller is the contact person at this location.

Attached, is a list of safety observations and recommendations based on conditions present at the time of my visit. If you have any questions or require additional information after reading this report, please don't hesitate to contact me.

Sincerely,

John Doe

John Doe President/Owner Safety-Reports, Inc. Phone: (402) 403-6575

Email: johndoe1963@cox.net

CC: Bill Johnson Tom Jackson

Observations and recommendations are purely advisory and based on practices and conditions observed and information provided at the time of this survey. They are not intended to include every loss or accident potential. It's the client's responsibility to make further observations and take whatever action that may be necessary to prevent losses, enforce safety procedures and eliminate hazardous conditions so as to comply with any federal, state, or local law, rule or regulation concerning safety and health.

General Industry Report

Completed for: Best Company
Report Name: General Industry
Location: Omaha, NE

Contact: Tim Miller, Shop Manager

Inspection Date: October 02, 2016

Scope of Work: Monthly Safety Walk-through

Score: 66%

Observations

Compressed Air

Observation Not all air nozzles are equipped with relief ports and/or relief ports are blocked

(1910.242)

Recommendation Only use air nozzles equipped with relief ports to discharge sufficient air to reduce the air

pressure at the nozzle tip to less than 30 p.s.i. [reference 1910.242(b)]. View OSHA

Standard

Responsible Party: Fabrication Manager

Photo(s)



Non approved air nozzle in fab shop



Example of an approved air nozzle



Example of an approved air nozzle



Non approved air nozzle

Compressed Gas Cylinders

Observation

Not all cylinders are secured to prevent tipping (1910.101)

Recommendation

Take appropriate steps to secure compressed gas cylinders in an upright position to prevent them from tipping over in accordance with Compressed Gas Association Pamphlet P-1-1965 [incorporated by reference in Sec. 1910.6]. View OSHA Standard

Notes: Cylinders need to be secured to prevent tipping in outside storage area.

Severity Rating: Moderate

Responsible Party: Maintenance Manager

Photo(s)





Proper Cylinder storage



Cylinders not secured to prevent tipping

Observation

Not all valve caps are replaced when cylinders are not in use (1910.101)

Recommendation

Take steps to ensure all valve caps are replaced on compressed gas cylinders when not in use in accordance with Compressed Gas Association Pamphlet P-1-1965 [incorporated by reference as specified in Sec. 1910.6]. View OSHA Standard

Notes: Safety caps are not replaced on all stored cylinders

Severity Rating: Moderate

Responsible Party: Fabrication Manager

Photo(s)



Safety cap missing

Cranes/Rigging

Observation

The rated load of each hoist is not marked and/or clearly legible from the ground or floor (1910.179)

Recommendation

Mark the rated load of the crane on each side of the crane and be sure it is clearly legible from the ground or floor [reference 1910.179(b)(5)]. View OSHA Standard

Photo(s)



Load limit on jib crane is not visible

Observation

Not all lifting hooks have functional safety latches (1910.179)

Recommendation

Visually inspect hooks daily for defects (i.e. twisted, pitted, throat opening too wide, broken/missing safety latch, etc.) and repair and/or replace hooks when defects are found [reference 1910.179(j)(2)(iii)]. View OSHA Standard

Severity Rating: Moderate

Responsible Party: Fabrication Manager

Photo(s)



Safety latch is broken on hook in Fab shop



Damaged hook in fab area



Non-approved lifting hook in Fab Shop

Observation

Slings are not maintained in good condition and/or they contain kinks or knots

Recommendation

Damaged or defective slings shall not be used. Additionally, slings shall not be shortened with knots or bolts or other makeshift devices and sling legs shall not be kinked. [reference 1910.184(c)(1),(2),&(3)] <u>View OSHA Standard</u>

Notes: Severely damaged sling should be removed from service

Severity Rating: Advisory

Responsible Party: Maintenance Manager

Photo(s)



Damaged sling

Electrical Safety

Observation Access to breaker panels, disconnects, etc. is obstructed (i.e. proper clearance not

maintained) and/or the area around transformers and other electrical equipment is

not kept clear. (1910.303)

Recommendation Take steps (i.e. paint lines on floor, use railing, cones, etc.) to maintain sufficient access

and working space (min. 30 inches wide by 36 inches deep) in front of all electric equipment including breaker panels, disconnect switches, transformers, etc. [reference

1910.303(g)(1)]. View OSHA Standard

Responsible Party: Maintenance Manager

Photo(s)





Blocked electrical panels

Blocked panels

Exits/Egress

Observation The direction of travel to exits is not marked when not apparent (1910.37)

Recommendation If the direction of travel to the exit or exit discharge is not immediately apparent, post

signs along the exit routes indicating the direction of travel to the nearest exit and exit

discharge [reference 1910.37(b)(4)]. View OSHA Standard

Responsible Party: Maintenance Manager

Observation Emergency lights are not provided and/or not all functional (1910.37)

Recommendation Install emergency lighting as needed to ensure adequate lighting of all exit routes and

doors during a power failure. Also, lighting should be tested monthly to ensure batteries are not dead or bulbs burned out. Repair/replace as needed [reference 1910.37(b)(1)].

View OSHA Standard

Notes: Need to inspect all emergency lights. At least two were found to not work when test button was depressed.

Responsible Party: Maintenance Manager

Photo(s)



Emergency lights not working when test button is depressed



Emergency lights not working above east door in warehouse

Flammable Liquids

Observation More than 25 gallons of Category 1 flammable liquids are stored outside of

approved storage cabinet or storage room (1910.106)

The quantity of Category 1 flammable liquids that may be located outside of an inside Recommendation storage room or storage cabinet in a building or in any one fire area of a building shall not

exceed 25 gallons. [reference 1910.106(e)(2)(ii)(b)(1)] View OSHA Standard

Responsible Party: Maintenance Manager

Photo(s)



Flammable not being stored properly



Flammable not stored properly

Grinders (Bench/Pedestal)

Observation The tongue guard is not adjusted to within 1/4 inch of wheel (1910.215)

Recommendation Adjust (or install if missing) the tongue guard on grinders to within one-fourth inch of the

wheel [reference 1910.215(b)(9)]. View OSHA Standard

Severity Rating: Moderate

Responsible Party: Maintenance Manager

Photo(s)



Tongue guard missing



Guards missing on bench grinder

Observation

Bench/pedestal grinders are not all permanently mounted (1910.212)

Recommendation

Make sure all equipment (i.e. bench or pedestal grinders) designed for a fixed location are securely anchored to prevent walking or moving [reference 1910.212(b)]. <u>View OSHA</u>
<u>Standard</u>

Severity Rating: Advisory

Responsible Party: Maintenance Manager

Photo(s)



Grinder is not mounted to bench top

Hazard Communication

Observation

Not all hazardous chemicals are properly labeled (1910.1200)

Recommendation

Take steps to ensure that all hazardous chemical containers (original and secondary containers) are properly labeled. Labels must not be removed or defaced [reference 1910.1200(b)(3)(i)]. <u>View OSHA Standard</u>

Responsible Party: Maintenance Manager

Photo(s)





Improper labeling

Improper labeling

Housekeeping

Observation

Not all work areas are kept clean and orderly (1910.141)

Recommendation

Take steps to ensure all places of employment are kept clean and organized to the extent that the nature of the work allows [reference 1910.141(a)(3)(i)]. <u>View OSHA Standard</u>

Photo(s)



Poor housekeeping in warehouse



Housekeeping issue in electrical room

Ladders (Portable)

Observation

Step ladder(s) found with missing or damaged non-slip safety feet (1910.26)

Recommendation

Immediately remove from service any step ladder that has damaged or missing non-slip feet [reference 1910.26(a)(3)(vii)]. <u>View OSHA Standard</u>

Photo(s)



Safety feet missing

Machine Guards (General)

Observation Not all point-of-operation hazards are properly guarded (1910.212)

Recommendation Install safeguards at the point of operation of machines to prevent employees from

placing a body part in the danger zone during the operating cycle [reference

1910.212(a)(3)(ii)]. View OSHA Standard

Responsible Party: Maintenance Manager

Photo(s)



Self-adjusting guard is bypassed

Observation Rotating parts hazards are not all properly guarded or shielded (1910.212)

Recommendation Install guards or shields on machines to prevent placing a body part in the rotating parts

hazard of a machine (i.e. chuck guard or shield on drill presses or lathes, fixed guard on rotating shaft, etc.) (reference 1910-212(a)/(2)/(ii)). View OSHA Standard

rotating shaft, etc.) [reference 1910.212(a)(3)(ii)]. View OSHA Standard

Responsible Party: Maintenance Manager

Photo(s)



Chuck guard needed on drill press

Medical Services/First Aid

Observation Issues relating to Medical/First Aid standards (1910.151) were identified (see

notes/photos for detail)

Recommendation Review OSHA regulations on Medical Services/First Aid (1910.151) and adhere to

applicable requirements in the standard. Reference comments, notes and/or photo(s) for

details. View OSHA Standard

Notes: Saline rinse bottles need to be inspected to ensure they are current/not expired.

Severity Rating: Advisory

Responsible Party: Warehouse Manager

Photo(s)



Saline rinse bottles are past expiration

Storage

Observation

Materials are not all stored/stacked safely (1910.176)

Recommendation

Materials in storage should be stacked, blocked, interlocked and limited in height so that they are stable and secure against sliding or collapse. Avoid leaning items on end unless secured to prevent them from falling over [reference 1910.176(b)]. View OSHA Standard

Responsible Party: Warehouse Manager

Photo(s)



Product stored in warehouse needs to be banded or use shrink wrap when staking on top shelf.

Tools (Hand & Power)

Observation

Tools are not all inspected and maintained in good condition (1910.242)

Recommendation

Require employees to inspect and maintain tools and equipment in a safe condition. Tag and remove from service any damaged or defective tools until repairs can be made or discard if repairs are not possible [reference 1910.242(a)]. View OSHA Standard

Responsible Party: Fabrication Manager, Maintenance Manager

Photo(s)





Damaged hammer

Damaged shaft on hammer

Observation

All angle grinders are not properly guarded (1910.243)

Recommendation

Require use of safety guards on portable angle grinders and the guard must be located between the operator and the wheel during use [reference 1910.243(c)(3)]. View OSHA Standard

Responsible Party: Fabrication Manager, Maintenance Manager

Photo(s)







Guard missing on angle grinder Guard missing on grinder

Guard missing on grinder

Welding, Cutting and Brazing

Observation

Adequate ventilation is not provided for welding operations (1910.252)

Recommendation

Provide local exhaust or general ventilating systems to keep the amount of welding fumes below the maximum allowable concentration as specified in 1910.1000 [reference 1910.252(c)(1)(iii)]. View OSHA Standard

Notes: Ventilation system in Maintenance Shop is suspect at best. Need IH to conduct testing to ensure proper ventilation is provided.

Responsible Party: Maintenance Manager

Closing Comments:

Several issues to address. Spoke to Tim regarding the results of this audit and he assured me steps will be taken to address deficiencies noted.

Submitted by: John Doe President/Owner Safety-Reports, Inc. (402) 403-6575 johndoe1963@cox.net

Observations and recommendations are purely advisory and based on practices and conditions observed and information provided at the time of this survey. They are not intended to include every loss or accident potential. It's the client's responsibility to make further observations and take whatever action that may be necessary to prevent losses, enforce safety procedures and eliminate hazardous conditions so as to comply with any federal, state, or local law, rule or regulation concerning safety and health.



Geo-Tag Information: Latitude: 41.268366 Longitude: -96.203879 Date: 10/02/2016

Time: 03:53 PM (central)

Inspection/report/audit verified by:

Sunday, October 02, 2016 15:52:13 PM (central)